


REPORT

TRUESDAIL LABORATORIES, INC.



CHEMISTS - MICROBIOLOGISTS - ENGINEERS
RESEARCH - DEVELOPMENT - TESTING

14201 FRANKLIN AVENUE
TUSTIN, CALIFORNIA 92680
AREA CODE 714 • 730-6239
AREA CODE 213 • 225-1564
CABLE: TRUELABS

CLIENT DOUGLAS AIRCRAFT COMPANY
Internal Mail Code 211-40
3855 Lakewood Boulevard
Long Beach, California 90846
SAMPLE Attention: Robert M. Tomko

DATE August 17, 1988
RECEIVED July 27, 1988
LABORATORY NO. 30419


INVESTIGATION Monthly Storm Drain Inspection, July 1988
Purchase Order Number T & M-23465-C

Monthly Analysis as Required by the C.R.W.Q.C.B. for
N.P.D.E.S. Permit Numbers CA 0001406 and CA 0001414

RESULTS

A representative of Truesdail Laboratories, Inc., tested the storm drain discharge on July 27, 1988 at the Douglas, Long Beach (003) and Torrance facilities. The discharge was tested for flow rate, pH and temperature. The results are as follows:

<u>SAMPLE IDENTIFICATION</u>	<u>DATE</u>	<u>TIME</u>	<u>FLOW-GPD</u>	<u>TEMP</u>	<u>pH</u>
Long Beach 003	7/27/88	2:30	101,088	76° F	9.0
Torrance	7/27/88	11:30	4,200	72° F	7.5



Respectfully submitted,

TRUESDAIL LABORATORIES, INC.

Luis Perez
Luis Perez, Supervisor
Industrial Waste

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from these Laboratories.